


MONUMENT RECORD

STATE OF INDIANA~COUNTY OF MONROE

Section: 27, Township: 8 NORTH, Range: 2 WEST,

Monument Description & Remarks: 1" PIPE FLUSH IN CENTERLINE OF ROAD



I, Eric Lee Deckard, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 8th day of OCTOBER, 2004 A.D.
 Completed by Steven V. Farkas, Monroe County Surveyor

Eric L. Deckard
 Indiana Registered Land Surveyor No. LS 29900012



STATE OF INDIANA - COUNTY OF MONROE

SECTION 27, TOWNSHIP 8 NORTH, RANGE 2 WEST

PIPE PLACED FLUSH IN CENTERLINE OF ROAD. NOT CHECKED TO
NORTH OR SOUTH, BUT CHECK-CHAINED TO EAST AND WEST 2641.41'
TO NW AND NE CORNERS OF SECTION 27.

STOP SIGN

28.68'

DUNLAP


ISON Rd

29.5'

NAIL WITH CAP IN POWER POLE

23.7'

PIPE FOUND



(●) AT CORNER



NOT TO SCALE

COUNTY OF MONROE

I, _____ HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS _____ DAY OF _____, 19 _____ A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO.

OR _____

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP:
VAN BUREN

CORNER I.D.

0 - 17

TITLE

SECTION 27
 TOWNSHIP 8N
 RANGE 2W
RS1000 2228

22

2641.41

2641.41

Van Bu-017

NW,NW	NE,NW	NW,NE	NE,NE
SW,NW	SE,NW	SW,NE	SE,NE
NW,SW	NE,SW	NW,SE	NE,SE
SW,SW	SE,SW	SW,SE	SE,SE

28

26

34

AZIMUTH and BEARING DATUM DESCRIPTION

DATE 10-24-74 SURVEY PARTY T. Daugherty - H. Sudbury

COMMENTS Pipe placed Flush in & of Road - not checked to North or South, but check-chained to East & West.

2641.41 to NW & NE Corners of Sec 27

REFERENCE SKETCH (use back if ness.)

